

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Error Is
1 BRS	L1	0	(captured adj pad) with mask	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:00			0
2 BRS	L2	22	captured adj pad	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:01			0
3 BRS	L3	108	"L22" and mask	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:00			0
4 BRS	L4	2	L2 and mask	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:00			0
5 BRS	L5	22	captured adj pad	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:03			0
6 BRS	L6	426	pad near mask	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:33			0
7 BRS	L7	140	L6 and (chip or solder)	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:19			0
8 BRS	L8	4843	pad with mask	USPAT; US-PGPU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 12:33			0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Error rs
9 BRS	L9	631	(pad with mask) same (solder or reflow)	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 12:34			0
10 BRS	L10	597	L9 not L6	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:35			0
11 BRS	L11	1609	438/612.ccls.	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:35			0
12 BRS	L12	446	L11 and mask	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:49			0
13 BRS	L13	212	438/613.ccls. and mask	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:52			0
14 BRS	L14	142	L13 not L12	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:50			0
15 BRS	L15	97	438/611.ccls. and mask	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:54			0
16 BRS	L16	185	438/98.ccls. and mask	OSPAT; US-PGPU B: EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:55			0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Error rs
17 BRS	L17	20	L16 and pad	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:56			0
18 BRS	L18	694	ellips with mask	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 14:06			0
19 BRS	L19	67	ellips near mask	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 13:57			0
20 BRS	L20	38	L18 and pad	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 14:30			0
21 BRS	L21	650	((ellips or shape) near opens) same mask	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 14:09	Truncation Overflow. Return string from Server is: 5'0'0'ELL	1	
22 BRS	L22	13	L18 and solder	USPAT; US-PGCU B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 14:30			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1 BRS	L1	72	361/743.ccls.	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 15:39			0
2 BRS	L2	701	251/738.ccls.	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 15:40			0
3 BRS	L3	235	L2 and mask	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:05			0
4 BRS	L4	285	251/737.ccls. and mask	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:17			0
5 BRS	L5	159	L4 not L3	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:05			0
6 BRS	L6	172	251/780.ccls. and mask	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:13			0
7 BRS	L7	177	251/786.ccls. and mask	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:14			0
8 BRS	L8	19	L7 and L6	USPAT; US-PGPR B; EPO; JPO; DERWENT ; IBM TDB	2002/02/08 16:16			0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Error Is
9 BRS	L9	123	257/779.ccls. and mask	USPAT; US-PGDU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 16:22			0
10 BRS	L10	89	257/678.ccls. and mask	USPAT; US-PGDU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 16:24			0
11 BRS	L11	87	174/263.ccls. and mask	USPAT; US-PGDU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 16:27			0
12 BRS	L12	0	24/864.ccls. and mask	USPAT; US-PGDU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 16:27			0
13 BRS	L13	0	24/853.ccls. and mask	USPAT; US-PGDU B; EPO; JPO; DERMENT ; IBM TDB	2002/02/08 16:27			0